Service Pricing Guide

A6 Sedan



A6 Sedan

Service Pricing Guide

Engine Code CYGA-140KW	12 mths / 15,000km*	24 mths / 30,000km*	36 mths / 45,000km*	48 mths / 60,000km*	60 mths / 75,000km*	72 mths / 90,000km*	84 mths / 105,000km*	96 mths / 120,000km*
Description								
Engine Oil	RM355.12	RM355.12						
Oil Filter	RM100.00	RM100.00						
Socket Head Bolt with Hexagon Socket Head	RM28.10	RM28.10						
Brake Fluid		RM129.00		RM129.00		RM129.00		RM129.00
Gear Oil				RM1,204.00				RM1,204.00
Sealing Plug				RM41.00				RM41.00
Air Filter				RM364.00				RM364.00
Air Con Filter	RM515.00	RM515.00						
Spark Plug				RM720.00				RM720.00
Parts RRP**	RM998.22	RM1,127.22	RM998.22	RM3,456.22	RM998.22	RM1,127.22	RM998.22	RM3,456.22
Labour RRP**	RM399.00	RM483.00	RM399.00	RM693.00	RM399.00	RM483.00	RM399.00	RM693.00
8% Service Tax	RM31.92	RM38.64	RM31.92	RM55.44	RM31.92	RM38.64	RM31.92	RM55.44
Total RRP**	RM1,429.14	RM1,648.86	RM1,429.14	RM4,204.66	RM1,429.14	RM1,648.86	RM1,429.14	RM4,204.66

Additional Item	Recommended Service Interval	Recommended Retail Price (RRP)
Fuel Additive	Every 15,000km	RM212.00
Air Con Filter	To change every 15,000km	RM515.00
Wiper Blade	Inspect and replace every 6 months (if required)	RM640.00

Updated as of April 2024.

^{**}Service price is based on annual intervals or mileage, whichever comes first.

**All prices shown are recommended retail price (RRP).

**PHS Automotive Malaysia Sdn Bhd reserves the rights to change prices and specifications without prior notice.

***Please contact your preferred Audi dealer for more information.

A6 Sedan

2.0 quattro **Service Pricing Guide**

Engine Code CYPA-185KW	12 mths / 15,000km*	24 mths / 30,000km*	36 mths / 45,000km*	48 mths / 60,000km*	60 mths / 75,000km*	72 mths / 90,000km*	84 mths / 105,000km*	96 mths / 120,000km*
Description								
Engine Oil	RM355.12	RM355.12						
Oil Filter	RM100.00	RM100.00						
Socket Head Bolt with Hexagon Socket Head	RM28.10	RM28.10						
Brake Fluid		RM129.00		RM129.00		RM129.00		RM129.00
Gear Oil				RM1,806.00				RM1,806.00
Filter Element				RM184.00				RM184.00
O-Ring				RM73.70				RM73.70
Air Filter				RM364.00				RM364.00
Air Con Filter	RM404.00	RM404.00						
Spark Plug				RM720.00				RM720.00
Parts RRP**	RM887.22	RM1,016.22	RM887.22	RM4,163.92	RM887.22	RM1,016.22	RM887.22	RM4,163.92
Labour RRP**	RM420.00	RM504.00	RM420.00	RM798.00	RM420.00	RM504.00	RM420.00	RM798.00
8% Service Tax	RM33.60	RM40.32	RM33.60	RM63.84	RM33.60	RM40.32	RM33.60	RM63.84
Total RRP**	RM1,340.82	RM1,560.54	RM1,340.82	RM5,025.76	RM1,340.82	RM1,560.54	RM1,340.82	RM5,025.76

Additional Item	Recommended Service Interval	Recommended Retail Price (RRP)
Fuel Additive	Every 15,000km	RM212.00
Air Con Filter	To change every 15,000km	RM515.00
Wiper Blade	Inspect and replace every 6 months (if required)	RM640.00

^{**}Service price is based on annual intervals or mileage, whichever comes first.

**All prices shown are recommended retail price (RRP).

**PHS Automotive Malaysia Sdn Bhd reserves the rights to change prices and specifications without prior notice.

***Please contact your preferred Audi dealer for more information.

A6 Sedan Hybrid

Service Pricing Guide

Engine Code CHJA-155KW	12 mths / 15,000km*	24 mths / 30,000km*	36 mths / 45,000km*	48 mths / 60,000km*	60 mths / 75,000km*	72 mths / 90,000km*	84 mths / 105,000km*	96 mths / 120,000km*
Description								
Engine Oil	RM355.12	RM355.12						
O-Ring	RM15.20	RM15.20						
Sealing Plug	RM28.10	RM28.10						
Oil Filter	RM123.00	RM123.00						
Brake Fluid		RM129.00		RM129.00		RM129.00		RM129.00
1 Set Oil Drain Plugs and Monitor Screws						RM740.00		
ATF (Automatic Transmission Fluid)						RM2,040.00		RM342.00
Filter Element				RM364.00				RM364.00
Filter Element for Fine Dust, Odour and Hazardous Emission Filtering	RM515.00	RM515.00						
Spark Plug 'Longlife'		RM720.00		RM720.00		RM720.00		RM720.00
Parts RRP**	RM1,036.42	RM1,885.42	RM1,036.42	RM2,249.42	RM1,036.42	RM4,665.42	RM1,036.42	RM2,249.42
Labour RRP**	RM441.00	RM651.00	RM441.00	RM651.00	RM441.00	RM756.00	RM441.00	RM651.00
8% Service Tax	RM35.28	RM52.08	RM35.28	RM52.08	RM35.28	RM60.48	RM35.28	RM52.08
Total RRP**	RM1,512.70	RM2,588.50	RM1,512.70	RM2,952.50	RM1,512.70	RM5,481.90	RM1,512.70	RM2,952.50

Additional Item	Recommended Service Interval	Recommended Retail Price (RRP)
Fuel Additive	Every 15,000km	RM212.00
Air Con Filter	To change every 15,000km	RM515.00
Wiper Blade	Inspect and replace every 6 months (if required)	RM640.00

Updated as of April 2024.

^{**}Please contact your preferred Audi dealer for more information.

A6 Sedan

3.0 quattro **Service Pricing Guide**

Engine Code CREC-245KW	12 mths / 15,000km*	24 mths / 30,000km*	36 mths / 45,000km*	48 mths / 60,000km*	60 mths / 75,000km*	72 mths / 90,000km*	84 mths / 105,000km*	96 mths / 120,000km*
Description								
Engine Oil	RM524.96	RM524.96						
Oil Filter	RM216.00	RM216.00						
O-Ring	RM15.20	RM15.20						
Brake Fluid		RM129.00		RM129.00		RM129.00		RM129.00
Gear Oil				RM1,806.00				RM1,806.00
Filter Element				RM184.00				RM184.00
O-Ring				RM92.30				RM92.30
Air Filter				RM367.00				RM367.00
Air Con Filter	RM515.00	RM515.00						
Spark Plug		RM900.00		RM900.00		RM900.00		RM900.00
V-Belt						RM912.00		
Parts RRP**	RM1,271.16	RM2,300.16	RM1,271.16	RM4,749.46	RM1,271.16	RM2,300.16	RM1,271.16	RM4,749.46
Labour RRP**	RM399.00	RM588.00	RM399.00	RM819.00	RM399.00	RM798.00	RM399.00	RM819.00
8% Service Tax	RM31.92	RM47.04	RM31.92	RM65.52	RM31.92	RM63.84	RM31.92	RM65.52
Total RRP**	RM1,702.08	RM2,935.20	RM1,702.08	RM5,633.98	RM1,702.08	RM3,162.00	RM1,702.08	RM5,633.98

Additional Item	Recommended Service Interval	Recommended Retail Price (RRP)
Fuel Additive	Every 15,000km	RM212.00
Air Con Filter	To change every 15,000km	RM404.00
Wiper Blade	Inspect and replace every 6 months (if required)	RM660.00

upuated as of APTIL 2024.

*Service price is based on annual intervals or mileage, whichever comes first.

**All prices shown are recommended retail price (RRP).

**PHS Automotive Malaysia Sdn Bhd reserves the rights to change prices and specifications without prior notice.

***Please contact your preferred Audi dealer for more information.